

SAFETY INSTRUCTIONS for on-site vehicles

WELCOME TO H+H DEUTSCHLAND

The health and safety of our staff and visitors are very important to us.

These safety instructions apply to everyone who enters our premises. Please make sure you follow them throughout your time at our sites.

SIGNING IN AND COLLECTION

Signing in

Before entering our manufacturing facilities, please register at reception in the administration building or at despatch.

Note to greeters

Staff responsible for collecting guests at reception should undertake relevant health and safety training before collecting their first guests, and then at least annually.

Please also note loading recommendations for our various products. These recommendations can be downloaded from our website.

Instructions issued by loading staff must be followed at all times.

All accidents and near-accidents must be reported to the loading staff.

TRUCK DELIVERIES

■ Delivery of sand/gravel/silt/filler



Check during unloading for roots, foreign bodies (stones etc.) and moisture. Wear a protective face mask if necessary.

Cleanliness during delivery. Remove any dirt immediately.

Delivery notes must be signed.

■ Delivery of pallets

Only pallets from H + H will be paid for. Defective pallets and other pallets will be invoiced or not reimbursed.

■ Delivery of lime



Due to lime's strong moisture-binding properties, tightly fitting goggles must be worn.



An eye wash station is available at the silos for emergencies.

SAFETY INSTRUCTIONS



High-viz waistcoat, helmet, safety shoes and safety goggles must be worn at all times.



Always wear long trousers in the loading area.



Be alert and always watch out for on-site vehicles, especially at crossroads. As a pedestrian, always keep a safe distance from the loading vehicles.

Make sure loading staff and forklift drivers can see you at all times.



No access for unauthorised persons.



Speed limit 10 km/h




Do not touch equipment or components.



No photography except with permission.



No smoking or naked flames in buildings.



Observe clearance height.



Machines may start automatically.



Restricted winter service -
Caution: Risk of slipping and tripping



Do not walk on the gratings.



Observe warning signals/signs.
Machines may start automatically.



Caution: Danger of collision:
After unloading, leave drive away
from silo immediately



Keep all facilities such as emergency exits/waste containers, etc. clear. Park only in designated or assigned parking spaces.

The visitors' car park is on the same level as the assembly point.

Persons under 18 years of age must stay inside the vehicle. Company forklifts and vehicles may not be used without written permission.

KEY PHONE NUMBERS

MANAGEMENT AT LIME SANDSTONE SITES:

BABENHAUSEN	+49 6073 728149
DEMMIN	+49 3998 275220
DRESDEN	+49 351 8178740
DURMERSHEIM	+49 7245 806450
HERZFELDE	+49 33434 44729
KAVELSTORF	+49 38208 62514
KRONAU	+49 7245 806450
NIEDERRIMSINGEN	+49 7668 9960810
HEALTH & SAFETY LIME SANDSTONE:	+49 173 5399320

MANAGEMENT AT AERATED CONCRETE SITES:

HAMM	+49 2388 3070139
LAUSSNITZ	+49 3520 551451
WITTENBORN I + II	+49 4554 700168
HEALTH & SAFETY AERATED CONCRETE:	+49 162 2008905

EMERGENCY SERVICES

**FIRE SERVICE/
AMBULANCE:** 112

POLICE: 110



Sammelstelle – im
Brandfall bitte dort
hinbegeben.



I confirm I have read and understood these safety instructions.

Place, date

Company name

Signature

Thank you for your cooperation. We wish you a safe and pleasant visit.